



## WELDING DETAIL OF PART 5

ELEVATION



END VIEW



Align holes in flange (5c) with plate (5a), such that, when 2 of part numbers 5 are assembled as shown in assembly, the two plates (5a) lie in the same plane.  
Mark mating holes with an indented dash.

## ASSEMBLY DETAIL

